



Zinc Oxide Protectant Spray

For Protection of "At Risk" Skin and the Management of Weepy & Denuded Skin




APPLICATION TIPS for Best Results

- **Shake bottle well** for 5 seconds prior to every use
- Cleanse area as per facility guidelines; pat dry to remove residual moisture
- Prior to use, **prime sprayer away from patient** into a disposable cloth or garbage can by pumping until consistent spray is achieved
- **Squeeze trigger quickly and with force** to ensure an even spray (insufficient pressure may result in a liquid stream versus a well-dispersed spray)
- **Hold the bottle 4-6 inches from skin** during application; **no rub-in is required**
- **A heavy coat is not needed;** over-application, although not harmful, may cause fluid to drip down skin
- Product will become more translucent as it dries
- Even though the area will not be all white, there will be adequate protection

Suggested
Spray Areas

Additional sprays
may be needed
depending on the
size of the area
being treated.



Crawford Healthcare Inc. | 2005 South Easton Rd. | Suite 203 | Doylestown, PA 18901
Tel 855-522-2211 | Email us.info@crawfordhealthcare.com
www.crawfordhealthcare.us